



INSB Class

Building
trust.
Shaping safety

Service Suppliers Document of Approval

Ref. Nr. of DOA: **DEV/DOA/RE/389/26**

Date: **12 August 2026**

This is to confirm that:

Messrs: **HELLAS MARINE ELECTRONICS**

Address: **85, Alimou Ave., 17455 Alimos, Greece**

Has been approved
by INSB Class for:

- Surveys and testing of radio communication equipment.
- Surveys and testing of automatic identification system (AIS).
- Annual performance testing of voyage data recorders (VDR) and simplified voyage data recorders (S-VDR).

For vessels classed and or certified by INSB Class, in accordance with the society's Rules and Regulations, the technical requirements as applicable and at the presence of an appointed INSB Class surveyor.

See **overleaf for approval details**, conditions and / or limitations, if any.

This **Document of Approval** is issued at Piraeus and is valid from **12/08/2026 to 11/08/2027**, subject to annual renewal provided the continued compliance with INSB Class established requirements.

For **INSB Class**,

Dimitrios Sfaragkoulis
Surveys Administrative Support Dpt.



F-4517-19



Verify DOA



ANNEX TO

DOA Ref. Nr. DEV/DOA/RE/389/26

Service Supplier:	HELLAS MARINE ELECTRONICS
Limitations, if any:	-
Operators / Inspectors Data:	As per submitted and kept data.
Description of Manufacturers / Models:	As per submitted and kept data.
Previous INSB Class DOA Ref. Nr.:	DEV/DOA/RE/376/25

Provisions:

- Service Suppliers are to keep records of the approved operators / technicians / inspectors including information on their training and experience for the services for which they are approved.
- Equipment used by the approved Service Suppliers shall be appropriate for their scope of work and must regularly tested and calibrated according to their ISO certified operating procedures.
- For categories of Service Suppliers that require certification from Manufacturers, Manufacturer's documentary evidence that the Service Supplier has been certified or licensed to service the particular makes and models of equipment should be retained at their care and responsibility.

This Document of Approval may be withdrawn if:

1. The services rendered have been improperly carried out or the results improperly reported.
2. The necessary provisions for the maintenance of the approval elapse.

